| | Approved For F se 2002/06/25 : CIA-RD CLASS/FED MESSA | |
|--|---|--|
| DATE | 99ØZ 27 JAN 61 SECRET | 5 6 |
| Ban har pelleri krandballerin biyasi k 2003 oo dellasjoner dag langballerin | | |
| | DIRECTOR | OPERATIONAL IMMEDIATE |
| PROM | 25X1A | |
| | OPS (1-2-3-4) | OPERATIONAL IMMEDIATE |
| ma | : S/C (5) | Consider All Research and To Talke and an adversarial control of the consideration of the consideration of the consideration of the constant o |
| | TOP 1/277 OT 111 (# | 1N-4412Ø |
| To the secondary dec | TOR: 1017Z 27 JAN 61 25X1A | enemanta de la valencia como como en c Como en como e |
| \$*C. | | dsv:1 Ø23 |
| , <u> </u> | | 25X1A |
| | A. MAINTENANCE RIGGED A TANK PRESSURE CHECK UTILIZING A KOLLSMAN | |
| | DIFFERENTIAL PRESS GAUGE INDICATING INCHES OF MERCURY. AUX TANK | |
| | PRESS PEAKED AT 2.1 INCH MERCURY AND MAINTAINED 1.95 INCH WHICH | |
| | CONVERTS TO .97 PSI. MAINS PEAKED AT 1.75 INCH THEN MAINTAINED | |
| | 1.7 INCH WHICH CONVERTS TO .85 PSI. INDICATES INADEQUATE PRESS | |
| | SOURCE, ACCORDING TO TECH ORDER. | |
| | B. POSSIBILITY EXISTS OF EITHER MALFUNC | CTIONING PRESSURE REG OR |
| 25X1/ | | |
| .0, | C. DOES NOT HAVE FACILITIES TO BENCH CHECK PRESSURE REG. | |
| | DO YOU DESIRE ANOTHER TEST FLIGHT WITH T | |
| | D. IF PARTS AND TECH ARE SENT SUGGEST PRESSURE REG, | |
| | SNIFFLE VALVE AND REQUEST 1 3/8 INCH SOCKET WRENCH. REG NBR IS | |
| | AIR RESEARCH PART NER 108136-9. DUAL SNIFFLE VALVE PART NER H-167-12. | |
| | IF POSSIBLE SUGGEST ALSO VINSON AIR SHUT | F OFF VALVE PART NBR A-50126-1, |
| | DIVE FLAP HYDRAULIC CYLINDER HAD SMALL LEAK WHEN ARRIVED 25X1A | |
| | BUT STOPPED FOR PRESENT. CYLINDER DIVE | |
| | | - y |
| | END OF MESSAGE | A A |